Appendix D – Street Lighting Lifecycle Plan

Introduction

- 1. The background to lifecycle plans, and the format of each, is described in Section 5. This appendix provides the lifecycle plan for street lighting columns.
- 2. Street lighting is divided into various categories for asset management purposes. The four main components of column, lantern, lamp and power supply have different needs but, broadly speaking, the needs of each lantern are similar as are the needs of each lamp type. The main consideration in terms of capital investment is column type. The following categories are used:

Category	Description		
Painted steel	Also includes columns which are galvanised and painted		
Galvanised steel	Refers to galvanised but not over-painted columns. This is the type of column currently being installed.		
Concrete	Amongst the oldest columns and vary in design and size		
Other	This includes aluminium, cast iron, wooden poles and brackets mounted on buildings etc.		

Levels of service

- 3. The desirable levels of service for this asset category are set out in the table below. Judgements on the four attributes of safety, serviceability, availability and condition are made based on the national code of practice, "Well-lit highways", and on the criteria described in Section 2. Customer feedback is via the NHT annual customer satisfaction survey.
- 4. This level of service is one which fully meets all aspirations whilst minimising whole-life cost. The lifecycle plan, in later sections, shows how different levels of available funding will influence the extent to which this desirable level of service can be achieved.

Attribute	Desired Standard	Performance measures
Safety	Roads and footways lit to the	Public satisfaction as
(Network	standard. Switch off, dimming	measured by NHT survey
Integrity.)	and part night lighting to be	
	introduced (as far as risk	
	assessments allow) taking into	
	account crime, anti-social	
	behaviour and traffic accidents.	
	Equipment used shall have low	
	levels of light pollution.	

Serviceability	Installations physically and electrically safe.	
Availability	All lights working as planned.	Local PI
Condition	Consistent with achieving minimum whole-life cost, in terms of preventative maintenance and column replacement	Defined standards met

5. Failure to respond adequately to any of these four dimensions of level of service will produce risk to the authority. The table below, which details the main risks, underlines the importance of responding properly to each.

Risk type	Description example					
Physical	Accidents caused by structural defects or failure to maintain					
	adequate structure.					
	Electrical risk to the public.					
	Injury to an operative working in the highway due to					
	incomplete records, particularly underground cable records,					
Business and	Legal proceedings for failing in duty of care					
financial risk	Increase in compensation payouts due to a rising number of					
	accidents and third party claims.					
	Fines imposed on the authority as a result of legal					
	proceedings.					
	Reduction in the net book value of the asset.					
Corporate	Ineffective or defective lighting reflecting on the overall					
image	image of the County Council					
Environmental	Greater energy use, and light spillage, from old equipment					

Asset base and characteristics

6. This asset grouping comprises all street lighting, including feeder pillars and all cabling that is owned by the County Council as highway authority. The tables below give brief details of the current lighting stock.

Column Type				
Column material	Number			
Mild steel painted	29980			
Mild steel galvanized	26251			
Mild steel paint & galv	458			
Mild steel 1 – total	56689			
Stainless steel	102			
Concrete	8150			
Aluminium	23			
Cast Iron	154			
Wood	1519			
Other	249			
All	66886			

	Lamps	
Lamp Type		
Low pressure sodium	Wattage	Number
	35	25045
	90	1605
High pressure sodium	50	5478
	70	14320
	100	5218
	150	10026
	250	3146
	400	236
Other	Various	1504
Total		66889

Control				
	Number			
Time switch – all night	0			
Tim switch – part night	0			
Photo cell – all night	50864			
Photo cell – part night	14994			
24 hour operation	218			
Dimmed equipment	813			
Total	66889			

Column material	Age (years)	Number of columns by column mounting height						
		4m (Or Less)	5m	6m	8m	10m	12m	Total Columns
Mild Steel	0-20	50	9431	14682	7373	5077	2002	38615
	21-30	3	7101	36	2351	1534	127	11152
-	31-40	3	4210	69	742	1099	46	6169
	Over 40		737	14	2			753
	Total	56	21479	14801	10468	7710	2175	56689
Stainless steel	0-20			92	1			93
-	21-30		4	5				9
Ļ	31-40							0
	Over 40							0
	Total	0	4	97	1	0	0	102
Concrete	0-20		3	5				8
	21-30		7		1			8
	31-40	3	5557	6	3	2		5571
	Over 40		2561	2				2563
	Total	3	8128	13	4	2	0	8150
Aluminium	0-20		1				1	16
(tubular and	21-30		1					1
Fabricated)	31-40		3	2				5
Tabileatea)	Over 40		1					1
	Total	0	6	2	0	0	1	23
Cast Iron	0-20	146		1				147
	21-30		1					1
-	31-40		6					6
	Over 40							0
	Total	146	7	1	0	0	0	154
Wood	0-20		154	54				208
Includes those	21-30		358					358
mounted on	31-40		938	3				941
electricity/	Over 40		12	-				12
Telecom poles	Total	0	1462	57	0	0	0	1519
Composite	0-20							0
Include fibre	21-30							0
glass and GRP	31-40							0
	Over 40							0
4	Total	0	0	0	0	0	0	0
Other*	0-20	214	2		12		, v	228
	21-30	- 17	10	1				11
	31-40		10					10
	Over 40		10					0
	Total	214	22	1	12	0	0	249
All	Total		31108			7712	2176	

7. During 2012 a research project is being undertaken to evaluate the use of LED road lighting lanterns. Considerations will surround the ability of the lantern to meet the Roadway Lighting design codes given in BSEN13201, ease of installation, ease of maintenance, aesthetic considerations, initial cost and whole life cost including energy consumption charges.

Asset condition and assessment

- 8. To assess the extent to which the desirable levels of service are met requires measurements covering the four dimensions of safety, availability, condition and serviceability. There are as yet no measures for serviceability, and these will be considered further in the next edition of the TAMP.
 - FrequencyClean, inspect and change lamp4 6 years depending upon lamp
typeStructural testInitially at "Action Age" and then
determined by the previous testElectrical test6 yearsVisual safety checkEvery visitScouting to check light operationalRural 4 weekly. Market towns and
urban area around Leicester City 2
weekly.
- 9. Regular inspections and checks are undertaken as shown in the table below.

- 10. All street lighting columns are regularly inspected. From 2006-2012 all known type 1805 and 1806 concrete columns were removed due to structural concerns. Other concrete columns, particularly types 10, X and NX, together with painted steel columns installed prior to 1990, are now showing signs of deterioration. During the 2011/12 financial year 251 lighting columns were identified as needing immediate replacement due to concerns surrounding their structural condition. Of these 137 were concrete lighting columns of the types already identified as being of concern. 114 were steel columns, up from 32 lighting columns per year during the 2004/5 financial year. This reflects the increasing age of the painted steel lighting column stock. Currently less than 3% of our painted steel stock are known to be over 40 years old. By 2017 approx 18% of our painted steel column stock (8% of our total stock) will be known to be more than 40 years old.
- 11. During the summer of 2011 two steel lighting columns, installed in 1984 and 1988, suffered catastrophic bracket failures. Investigations have shown these failures to be associated with a particular bracket type. Work is currently ongoing to ascertain the

quantity and locations of this type of steel column. Future funding will be targeted towards the types of steel and concrete columns mentioned above. On a more positive note, other types of concrete column continue to perform well and repairs, such as sleeving, can extend the life of the lighting column for some years.

Structural Testing

- 12. Street lighting columns are tested once they reach their "Action Age". This date is determined by the location of the column, its surface protection, wind exposure and any attachments fitted to the column. Generally the "action age" is around 20 years after installation. After this initial test subsequent tests are undertaken every 3, 2 or 1 year, depending upon the results of the previous test. Steel lighting columns are visually inspected with an endoscope and ultrasonic material thickness testing is carried out if the endoscope reveals a potential problem. Concrete columns are visually tested. The Council also has lighting brackets mounted on Electricity Board wooden poles, bridges and other buildings and structures not owned by the council. Structural testing only ascertains if the bracket (and ancillary equipment) fixing to these structures is sound. Maintenance of the structure itself is the responsibility of others.
- 13. Detailed analysis of the results has shown that different types of lighting columns have different structural problems. Testing of steel lighting columns has shown considerable variability of lighting column condition in any one location. The main cause of failure is internal corrosion and our practice is to replace only those steel columns which fail the test. Our analysis has shown that this amounts to approximately 0.37% of painted steel columns in 2010/11.
- 14. A visual safety check of the condition of each lighting column is carried out on every visit. Lighting columns thought to be structurally unsound are further assessed and may be subject to an emergency "make safe" or are replaced in the shortest possible time.

Electrical Testing

15. Electrical testing of each lighting column, feeder pillar and council-owned cable network is carried out every six years in accordance with the IEE regulations. Test results are checked and defects programmed to be rectified.

Asset valuation

16. Appendix E details the approach taken to asset valuation. The initial net value (depreciated cost) of the street lighting asset is £56million

Future changes in demand

17. In recent years capital funding has been targeted towards replacement of existing stock rather than provision of more lighting. From the start of LTP3 limited funds are being

directed to street lighting improvements that will assist residents to access the services they require. The Community Access Lighting budget is being targeted at improvements to lighting around bus stops, shops and community areas.

18. Major new development is planned in the county over the next twenty years. This expansion will bring substantial lengths of new highway in new housing and employment areas, with attendant street lighting. The increase in the asset base will produce a requirement for additional maintenance expenditure, and in the long term an increased need for replacement.

Treatment options and costs

19. The limited number of types of lighting installation, and ways in which they deteriorate, lead to a relatively short list of maintenance treatments. These are summarised in the table below. Short-term treatments are dictated by safety and serviceability requirements. Decisions on when to intervene with medium and long-term treatments are determined in accordance with the asset management strategy.

Work category	Interval	Unit cost (£)			
Steel columns					
Replacement	40 years	800.00			
Concrete columns					
Sleeving	As Required	250.00			
Replacement	40 years	800.00			
Lamps					
Reactive replacement	As required	15.00			
Programmed replacement	4 -6 years	12.00			
Lanterns					
Reactive Replacement	As required	150.00			
Replacement	With column	inc in col cost			
Electrical components					
Reactive repairs	As required	6 plus component			
		cost			

Column Painting

20. Whilst new lighting columns are fully galvanised and have additional root protection, older steel columns had only aluminium or zinc spray coating which was then overpainted. The existing painted columns will continue to deteriorate and will initially become visually unsightly. Surface rust will then corrode the parent metal, weakening the structure. However, these lighting columns also corrode on the inside as the internal surfaces of the tube are not protected. Painting will not therefore significantly extend life expectancy of these ungalvanised steel columns.

Column sleeving

21. This can extend the life of some types of concrete column. Structural testing has shown that later styles of concrete columns have structural concerns along the length of the shaft. As a result, sleeving works are now being restricted to older type 7 columns that had a more substantial base and shaft construction. The majority of type 7 columns have now been sleeved and can be expected to last for a considerable time.

Lamp replacement

22. Different lamp types have a different mean life. Therefore the bulk lamp change is undertaken at 4 – 6 year intervals, depending upon the lamp survival curves for each lamp type. Longer periods between replacement lead to more expensive reactive replacements or increased outages. Shorter periods do not maximise lamp life. If the decision is taken to use LED lamps in future then these lamps will not require a bulk lamp change.

Management strategy for minimising whole-life costs

- 23. Whole life costs include not only the direct costs of works, design and supervision testing and inspections, but also the indirect costs caused by sub-optimal maintenance regimes, including inconvenience to users, environmental impacts and third party claims. The main factors which will affect the whole life cost of an individual installation are:
 - Type and quality of construction
 - Degree and type of damage and degradation
 - Age of components
 - Speed and quality of response to damage and degradation
 - Timing of intervention and quality of medium and long term treatments
- 24. At present, the links between these have not been fully quantified. This is an important area for research and development and progress nationally will be used to inform policy decisions. The evolution of the LED lamp for street lighting applications will soon become a viable alternative. These options will also be considered at the appropriate time.

25. Historically the County Council's strategy for maintaining street lighting has been:-

- To look for a high standard of initial installation
- To carry out electrical and structural testing of units
- To undertake 'night patrols' for inoperative lighting
- To undertake reactive maintenance works expeditiously to prevent short term deterioration and keep in a safe condition.
- To maintain an up-to-date inventory of lighting stock to facilitate maintenance management and enable competitive purchase of energy.
- To bulk-change lamps to maintain light output at satisfactory levels.
- To replace life-expired columns within budget availability, with a particular emphasis on replacing life-expired concrete columns
- 26. This strategy is based on good practice. However, the sums allocated for column replacement historically have not been adequate, resulting in a backlog of lighting columns needing replacement. During the LTP2 period significant investment was introduced into this area and the backlog of lighting columns requiring replacement was reduced from 19.8% to 10.16%. The information that has come to light during the LTP2 period in relation to steel lighting column failures has dictated a revised methodology for the calculation of the backlog of lighting column replacement for LTP3. At the start of LTP3 the backlog was recalculated to 11.04% of lighting columns needing replacement using the new methodology. Investment in 2011/12 reduced this backlog to 8.4%. Further investment is required to remove those remaining lighting columns that are of structural concern and achieve our desired steady state replacement rate of 2.5%.

LTP3 proposals to 2016/17

27. The remaining Type 10, type X and Type NX concrete columns are in need of replacement. In addition, based upon previous experience with painted steel columns, 150 steel painted columns are predicted to need replacement in each of the following 5 years. Further significant investment is planned over the period 2012/13 to 2016/17 to aim reduce this backlog to a steady state backlog of 2.5%.

The following table details the minimum lighting column replacement needs, and the proposed minimum number of lighting column replacements for the LTP3 period up to 2016/17.

Column Type	Total Number	No. life- expired at June 2012	No. to be replaced before March 2017	No. of life expired at end of March 2017
Painted Steel	29980	150	750	4859
Galvanised Steel	26709	0	0	0
Concrete "x"	392	392	392	0
Concrete "nx"	253	253	253	0
Concrete 10	4823	4823	4823	0
Concrete 7	2394	0	0	uncertain
Other	2335	0	0	0
Total	66889	5618	6218	4859 +

28. During the next 5 years continued monitoring of the painted steel lighting stock will be undertaken. Should an increased spend be required in this area this will be highlighted. After 2016/17 a new calculation methodology will be required to address the concerns that have developed over the next 5 years. On a pure age calculation approx 4850 additional painted steel lighting columns will be in excess of 40 years old and will probably require replacement.

Alternative options

29. Some authorities have sought to address the problem of replacing ageing lighting columns through PFI. Leicestershire reviewed the possibility of a PFI and a joint PFI with Derbyshire and Nottinghamshire. The affordability gap for both options was too large for these to be pursued.

Risks

30. The risks involved in implementing the lifecycle action plan have been assessed against the council's standard grid of likelihood versus impact and are detailed in the table below, with an outline of the mitigation to be planned. The 'red' risks are listed in section 7 of the main TAMP document.



Likelihood of causes

Risk	Level	Mitigation	Responsible	
1. Insufficient staff resources for	2B	Use resources	GM (Highway	
bulk column replacement scheme		from URS if	Management)	
design work during 2012/13		required		
2. Insufficient LHO resource to	3C	Use resources	GM (Highway	
deliver agreed programme in		available via	Management)	
2012/13		Tarmac.		

29th June 2012.