

Advisory: Safety gloves, no shorts or short sleeve tops

We Do Not Accept the Following Waste Types:

- GAS BOTTLES / FIRE EXTINGUISHERS
- TREE TRUNKS OR STUMPS
- BEER KEGS
- INDUSTRIAL FRIDGE/FREEZERS
- MIXED LOADS CONTAINING PLASTERBOARD
- CAR BATTERIES
- SAWDUST (or any dust)

- PAINT, OILS OR OTHER LIQUIDS
- BLUE CHEP PALLETS
- FLUORESCENT TUBES
- TYRES
- ALLOY WHEELS
- RADIOACTIVE OR EXPLOSIVE WASTE

Instructions

- 1. All vehicles MUST report to the weighbridge to weigh "IN" and "OUT" prior to entering or leaving the site
- 2. All occupants of the vehicle should be wearing correct PPE, including high visibility clothing & steel toe capped boots (ideally shoes with steel midsole). Anyone refusing to wear the correct PPE will be refused entry to the site. PPE to be worn until the site has been exited
- 3. Drivers must advise what waste they are wanting to tip
- 4. NO vehicle to proceed onto site until authorised by the weighbridge operator (either verbally or by being waved off the bridge), then please proceed as directed
- 5. Drivers MUST abide by the site speed limit of 5mph at all times
- 6. DO NOT use mobile phones whilst on the site at any point
- 7. DO NOT smoke or vape within your vehicle cabs or inside the site at any time
- 8. Dogs need to be tethered or restrained by a lead to the inside of the vehicle to ensure they do not escape
- 9. Beware of moving vehicles / mobile plant on site at all times
- 10. No children under the age of 16 to be in operational areas
- 11. Follow the direction of the weighbridge staff and the waste transfer staff at all times
- 12. In case of fire or other emergency please follow the instructions from the site staff or the weighbridge staff and go to the fire assembly point located near the entrance gates and indicated by the sign
- 13. Always report any spillages, incidents, accidents or near misses to a member of site staff or the weighbridge staff

Instructions of site staff or weighbridge staff are final and must be followed